

**The Appendix is an integral part of  
Certificate of Accreditation No. 247/2022 of 25/05/2022**

**Accredited entity according to ČSN EN ISO/IEC 17020:2012:**

**Foster Bohemia s.r.o.**  
Inspection Body  
Krátká 1148/32, Strašnice, 100 00 Praha 10

Ordinal number	Inspection field	Inspection type and scope	Inspection procedure
1	Detection of presence and determination of asbestos and other dangerous fibres in indoor and outdoor environment and risk analysis.	Indoor and outdoor environment:  - Detection of presence of materials containing asbestos or other dangerous fibres,  - Determination of extent of presence of materials containing asbestos or other dangerous fibres,  - Determination of extent of presence of materials containing asbestos or other dangerous fibres together with the determination of the degree of hazard.	IP01 version 10/05/2017  IP01 - 3.1  IP01 - 3.2  IP01 - 3.3
2	Inspection of efficiency of removal of asbestos and other dangerous fibres in indoor and outdoor environment.	Indoor and outdoor environment.	IP02 version 16/05/2014

**Explanations and abbreviations:**

IP - Inspection Procedure (In-house inspection procedure prepared by IO Foster Bohemia s.r.o.)