

**The Appendix is an integral part of
Certificate of Accreditation No. 640/2021 of 07/12/2021**

Accredited entity according to ČSN EN ISO/IEC 17025:2018:

GAMALUX Plzeň spol. s r.o.
Testing Laboratory for Non-Destructive Testing
Doudlevecká 2924/50, 301 00 Plzeň

Tests:

Ordinal number ¹	Test procedure / method name	Test procedure / method identification ²	Tested object
1*	Radiographic test	ČSN EN ISO 17636-1, ČSN EN 12681-1, ČSN EN ISO 5579	Welded products, castings
2*	Ultrasonic test	ČSN EN 16810, ČSN EN 10160, ČSN EN 10307, ČSN EN 10308, ČSN EN 10228-3, ČSN EN 10228-4, ČSN EN ISO 17640, ČSN EN 12680-1, ČSN EN 12680-2, ČSN EN 12680-3, ČSN EN ISO 16809 ČSN EN ISO 13588, ČSN EN ISO 10863	Welded products, forgings, rolled products, castings
3*	Visual test	ČSN EN ISO 17637, ČSN EN 13018, ČSN EN 1370, ČSN EN 10163-1	Welded products, forgings, rolled products, castings
4*	Penetrant test	ČSN EN ISO 3452-1, ČSN EN 1371-1, ČSN EN 10228-2	Welded products, forgings, rolled products, castings
5*	Magnetic particle test	ČSN EN ISO 17638, ČSN EN 1369, ČSN EN 10228-1	Welded products, forgings, rolled products, castings

¹ asterisk at the ordinal number identifies the tests, which the Laboratory is qualified to carry out outside the permanent laboratory premises

² if the document identifying the test procedure is dated, only these specific procedures are used. If the document identifying the test procedure is not dated, the latest edition of the specified procedure is used (including any changes)